STATE OF MICHIGAN



THOMAS J. ANDERSON
E. R. CAROLLO
JACOB A. HOEFER

JAMES J. BLANCHARD, Governor

S.E. Michigan Field Office 15500 Sheldon Road Northville, MI 48167

DEPARTMENT OF NATURAL RESOURCES

RONALD O. SKOOG, Director

October 17, 1985

Burroughs Corporation 41100 Plymouth Road Plymouth, MI 48170 Attn: Richard Terlaak

RE: MID 005358965

NATURAL RESOURCES COMMISSION

STEPHEN F. MONSMA

HILARY F. SNELL PAUL H. WENDLER HARRY H. WHITELEY

Dear Mr. Terlaak:

On October 15, 1985, acting as a representative of the United States Environmental Protection Agency, I performed an inspection of your facility located at the above address to evaluate compliance of that facility with the requirements of Subtitle C of the Resource Conservation and Recovery Act (RCRA) as amended.

As a result of that investigation, it was determined that your facility qualifies for the small quantity generator status outlined in 40 CFR §261.5 (see attachment) and is in compliance with RCRA. If 1,000 kilograms (2,200 pounds) of hazardous waste is generated per month or is on-site at any time, the facility is subject to the generator standards outlined in 40 CFR Part 262.

Michigan's Hazardous Waste Management Act states that if more than 100 kilograms (220 pounds) of hazardous waste is generated in a calendar month or accumulated at any time, the waste must be disposed of at a facility licensed under the Act.

All liquid industrial waste removed from your facility by another firm must be with a licensed liquid industrial waste hauler and you must use the manifest reporting form.

It is recommended you notify the United States Environmental Protection Agency of your status as a small quantity generator in accordance with the attached small quantity generator information sheet.

If you have any questions, please feel free to contact me at (313) 459-9180.

Sincerely.

Kenneth L. Damrel Environmental Engineer HAZARDOUS WASTE DIVISION

Kenneth L Damel

cc: U.S. EPA, Region V B. Okwumabua



RCRA INSPECTION REPORT

EPA Identification Number: $M \equiv D$	00535	8965
Installation Name: Burrou	ghs Corporation	
Location Address: 4/100	Plymouth Rd.	
city: Plymouth	State: MI 48	170
Date of Inspection $10/15/85$	Time of Inspection (fro	m) <u>10:30</u> (to) <u>11:30</u>
Person(s) Interviewed Richard Terlaak	Title Env. Coordinator	Telephone 313-453-1400
Inspector(s) Kenneth L. Damrel	Agency/Title MDNR/HWD/Env.Eng	Telephone . 313-459-9180
Installation Activity (mark only one box))	Inspection Form(s)
Treatment/Storage/Disposal per 40 CF Generation and/or Transportation	FR §265.1 and/or	Α
Treatment/Storage/Disposal (No Gener	ration or Transportation)	·A
Generation and Transportation		B,C
Generation Only		В
Transportation Only		С
None of the above. The facility is a	small quanti	ty generate

STATE OF MICHIGAN



NATURAL RESOURCES COMMISSION

JACOB A. HOEFER ROBERT HOLMES E. M. LAITALA HILARY F. SNELL PAUL H. WENDLER HARRY H. WHITELEY

JAMES J. BLANCHARD, Governor

DEPARTMENT OF NATURAL RESOURCES

STEVENS T. MASON BUILDING
BOX 30028
LANSING, MI 48909
HOWARD A. TANNER, Director
Hazardous Waste Division
9311 Groh Road
Grosse Ile, Michigan 48138

July 6, 1983

Mr. Raymond P. Dewyer Manager, Safety and Security Burroughs Corporation 41100 Plymouth Road Plymouth, Michigan 48170

Re: MID 005358965

Dear Mr. Dewyer:

Thank you for your letter of June 24, 1983, which discusses the training program for personnel handling hazardous wastes at the Burroughs Plymouth Plant. It appears to meet the requirements of 40 CFR 265.16 quite completely. I appreciate that you and the plant staff have chosen to deal with this area so thoughtfully and constructively.

Sincerely,

Susan Norton

Susan Norton Water Quality Specialist Compliance Section Hazardous Waste Division

SN/sc

cc: Hazardous Waste Division, Lansing (3)

1

PLYMOUTH PLANT
41100 PLYMOUTH ROAD, PLYMOUTH, MICHIGAN 48170

June 24, 1983

RECEIVED

Susan Norton, Water Quality Specialist Department of Natural Resources Compliance Section Hazardous Waste Division Detroit Area 9311 Groh Road Grosse Ile, Michigan 48138

JUN 27 1983

WATER QUALITY DIV.

RE:

MID 005358965

February 2, 1983 RCRA Inspection

Dear Ms. Norton:

My apology for this late reporting of the correction of Item 4 (Personnel Training), but I hope that you will agree that it was worth the wait.

Please find attached our new Hazardous Waste Handling and Disposal policy. As it indicates, both the <u>handlers</u> and their <u>supervisors</u> must receive training by this office in order to be licensed for the handling of Hazardous Wastes.

The initial retraining and licensing process has been completed and we will be retraining all persons on a 6-month basis. Both the policy and the training program have been well received by the Union and Plant Management.

Should you have any questions in this regard, please feel free to contact me.

Sincerely,

R. P. Dewyer, Manager Safety & Security

Plymouth Plant

Attachment.

9467-8-83 A

STATE OF MICHIGAN

NATURAL RESOURCES COMMISSION

JACOB A. HOEFER
E. M. LAITALA
HILARY F. SNELL
PAUL H. WENDLER
HARRY H. WHITELEY
JOAN L. WOLFE
CHARLES G. YOUNGLOVE

James Blanchard, Governor

DEPARTMENT OF NATURAL RESOURCES

STEVENS T. MASON BUILDING
BOX 30028
LANSING, MI 48909
HOWARD A. TANNER, Director
Hazardous Waste Division
Detroit Area
9311 Groh Road
Grosse Ile, Michigan 48138

April 19, 1983

Mr. Raymond P. Dewyer
Manager, Safety and Security
Burroughs Corporation
41100 Plymouth Road
Plymouth, Michigan 48170

Re: MID 005358965

Dear Mr. Dewyer:

Thank you for your letter of April 11, 1983, documenting corrections to the deficiencies noted during the RCRA inspection of February 2, 1983. It appears to address Items 1-3 and 5 of our letter adequately. We request that you respond by letter no later than May 31, 1983, indicating how Item 4 (Personnel Training) has been corrected.

Again, please feel free to call this office should any further questions arise. Your continued cooperation in resolving this matter is appreciated.

Sincerely,

Kenneth Burda, P.E. Area Engineer

Susan Norton
Water Quality Specialist
Compliance Section
Hazardous Waste Division

KB:SN/sc

cc: Hazardous Waste Division, Lansing (3)

1

PLYMOUTH PLANT
41100 PLYMOUTH ROAD, PLYMOUTH, MICHIGAN 48170

April 11, 1983

RECEIVED

APR 18 1983

Susan Norton Department of Natural Resources Hazardous Waste Division 9311 Groh Road Gross Isle, Michigan 48138 WATER QUALITY DIV, DIST. I

RE: MID 005358965 - BURROUGHS PLYMOUTH PLANT
(Your February 10, 1983 Letter)

Dear Ms. Norton:

Pursuant to our April 6, phone conversation, all deficiencies enumerated in the subject letter except for No. 4 (Personnel Training) have been corrected. Positive steps have been instituted to assure against any reoccurrence of these deficiencies.

The Personnel Training issue has proven to be a thornier issue than expected. I hope to have the issue resolved and this training completed within the next 5-6 weeks. I will notify you when this last deficiency is corrected.

Should you have questions in this regard, please contact me.

Sincerely,

R. P. Dewyer

Manager, Safety & Security

Plymouth Plant



NATURAL_RESOURCES COMMISSION

JACOB A. HOEFER
CARL T. JOHNSON
E.M. LAITALA
HILARY F. SNELL
HARRY H. WHITELEY
JOAN L. WOLFE
CHARLES G. YOUNGLOVE

WILLIAM G. MILLIKEN, Governor

STEVENS T. MASON BUILDING BOX 30028 LANSING, MI 48909

DEPARTMENT OF NATURAL RESOURCES

Howard A. TANNER, Director
Hazardous Waste Division
Detroit Area
9311 Groh Road
Grosse Ile, Michigan 48138



February 10, 1983

CERTIFIED MAIL

Mr. Raymond P. Dewyer Manager, Safety and Security Burroughs Corporation 41100 Plymouth Road Plymouth, Michigan 48170

RE: MID 005358965

Dear Mr. Dewyer:

On February 2, 1983, Susan Norton of this office inspected the Burroughs Plymouth Plant to determine compliance with the provisions of the Resource Conservation and Recovery Act (RCRA) of 1976, as amended. The inspection indicated the following deficiencies:

- 1. Some of the drums at the hazardous waste storage pad were not completely packaged or labelled in accordance with Department of Transportation regulations. This is in violation of 40 CFR 262.30, 262.31, and 262.32.
- 2. Not all drums of waste at the storage pad were marked with the date on which the period of accumulation began. This is contrary to the provisions of 40 CFR 262.34(a)(2).
- 3. Not all the drums at the storage pad were marked with the words "Hazardous Wastes". This is in violation of the requirements of 40 CFR 262.34(a)(3).
- 4. Concerning personnel training records, there was no written record that individuals initially trained in 1980 have received an annual review at any time since. Further, there should be documentation that each individual who handles hazardous waste has been trained, not simply his supervisor. These requirements are discussed in 40 CFR 265.16 (incorporated by reference in Part 262, Standards for Generators).
- 5. There was no hazardous waste Contingency Plan available for inspection. This is required by reference in the Generator Standards to 40 CFR 265.50 and 265.51.



Mr. Raymond P. Dewyer February 10, 1983 Page 2

We request that you respond by letter no later than March 11, 1983, documenting what actions you have taken to correct the above deficiencies. A copy of the RCRA inspection report is enclosed for your examination. Should you have any questions, please do not hesitate to call us at (313) 675-0860. We wish to thank you for your time and cooperation during the inspection.

Sincerely,

Kenneth Burda, P.E. Area Engineer

Susan Norton

Susan Norton

Water Quality Specialist

Compliance Section

Hazardous Waste Division

KB:SN/sn Enclosure

cc: Hazardous Waste Division, Lansing (3)

*1335

RCRA Inspection Report

tra Identification Number: M / D	_ <u>00535</u>	9 6 5
Installation Name: BURROVENS CORPO	ed tion	-
Location Address: 41100 PLYMOUTH	Ro.	
City: PLYMOUTH	State: MICNIGAN 48170	2
Date of inspection: FEB. 2,1983	Time of inspection (from)	Z:35P.M. (to) 5:10P.M.
Person(s) interviewed	Title	Tel ephone
MR. RAHMOND P. DEWYER MOR., S	AFETY & SECURITY	313 - 453 - 1400, Ext 4818
Inspector(s) Susan Norton, Mich Deft. CFNATE RE	Agency/Title SOURCES - NAZ. WASTE DIV	Tel ephone 5/3 - 675-0860
Installation Activity (mark only one	box)	Inspection Form(s)
Treatment/Storage/Disposal per 40 Generation and/or Transportation	CFR 265.1 and/or	A
Treatment/Storage/Disposal (no ge	neration or Transportation)	A
☐ Generation and Transportation		B, C
M Generation only		B
		C

m10005358965

INSPECTION FORM B

Section	Α:	Scope	of	inspection

Standards for generators of HAZARDOUS WASTE subject to 40 CFR 262.10

Section B: MANIFEST REQUIREMENTS (Part 262, Subpart B)

			•				
		-	Yes	No	NI*	Remarks	
(1)	Does ava	s the generator have copies of the manifest ilable for review? 262.40	×				
(2)	mon	mine manifests for shipments in past 6 ths. Indicate approximate number of ifested shipments during that period.	·····	-			
(3)	fol' cop	the manifest forms examined contain the lowing information? (If possible, make 262 ies of, or record information from, manifests t do not contain the critical elements)			a Cantillo Calon (Calon Calon Ca	**************************************	
	ā•	Manifest document number?	X				
	ь.	Name, mailing address, telephone number, and EPA ID number of generator?	×			C-Ferring Control of the Control of	
	c.	Name and EPA ID number of transporter(s)?	- <u>X</u>		·		
	d.	Name, Address, and EPA ID Number of designate permitted facility and alternate facility?	ted <u>×</u>				
	e.	The description of the waste(s) (DOT shippiname, DOT hazard class, DOT identification number)?	ng · <u>×</u>	- 6			
	f.	The total quantity of waste(s) and the type and number of containers loaded?	X	-	<u> </u>		
	g.	Required certification?	×			**************************************	
	h.	Required signatures?	<u> x</u>				
(4)	Rep	ortable exceptions 262.42				·	
	ā.	For manifests examined in (2) (except for swithin the last 35 days), enter the number fests for which the generator has NOT receiving signed copy from the designated facility will days of the date of shipment.	of mar	ni-		77 00 77051	
	b.	For manifests indicated in (4a), enter the which the generator has submitted exception (40 CFR 262.42) to the Regional Administrat	repor	rts		-	

Section C - PRE-TRANSPORT REQUIREMENTS (40 CFR Part 262 Subpart C)

		- -	162	ИО	NI	Remarks
(1)	regulat:	e packaged in accordance with DOT ions? (Required prior to movement rdous waste off-site) 262.30		<u>X</u>	Terrelatura shill a sissanin	
(2)	accordar hazardou	te packages marked and <u>labeled</u> in nce with DOT regulations concerning us waste materials? (Required prior ment of hazardous waste off-site)	262.31	and \underline{X}	262.32	
(3)	If requi	ired, are placards available to rter? 262.33	×			
(4)	Pre-ship	oment Accumulation:				
a pe	ies only rmit. Th site.	to GENERATORS that store hazardous was nese items do not apply to generators	aste oi whose	n-sit wast	e for 9 e is in	90 days or less without transported
		hazardous waste accumulated in con- ners? If no, skip to b. 262.34	<u>×</u>			
	i.	Is each container clearly marked wit the date on which the period of accumulation began?	h 	×	u de la composition della comp	U.I. TRICNLORDETNANE - DRUMS
	ii.	Have more than 90 days elapsed since the dates marked?		?	Withholes and a	CAN'T TELL -
	iii.	Is each container labeled or marked clearly with the words "Hazardous Wastes?"		×	. 	
	iv.	Are containers in good condition?	X			
	٧.	Are containers compatible with waste in them?	X	• • • • • • • • • • • • • • • • • • •		
	vi.	Are containers managed to prevent leaks?	X	Note the second designation of the second de		ggregorial Administration or synchronists or gradual and company of the second
	vii.	Are containers stored closed?	X			
	viii.	Are containers inspected weekly for leaks and defects?	<u>X</u> _	-	***	
·	îx.	Are ignitable and reactive wastes st at least 15 meters (50 feet) from th facility property line? (Indicate if waste is ignitable or reactive).	e		-	

	<u>-</u>	res i	10	И1.	Remarks
х.	Are incompatible wastes stored in separate containers? (If not, the provisions of 40 CFR 265.17(b) apply.)	Bi	47 49.710.111	American construction of the construction of t	NA
Xi.	Are containers of incompatible waste separated or protected from each other by physical barriers or sufficient distance?		***************************************		N/A
	hazardous waste accumulated in tanks? no, skip to c. 262.34 (January 11, 1982 revision)		X		THIS SECTION NOT
i.	Is each tank labeled or marked clearly with the words "Hazardous Wastes"? 262.34 (January 1982 revision)	- 1/15/-1			APPLICABLE
ii.				Politic Politicalism	
iii.	Do uncovered tanks have at least 60 cm (2 feet) of freeboard, or dikes or other containment structures?				
iv.	Do continuous feed systems have a waste-feed cutoff?	- O-rifferenteid (P-mil	<u> </u>	k	
٧.	Are waste analyses done before the tanks are used to store a substantially different waste than before? 265.193	nt —			-
vi.	Are required daily and weekly inspections done? 265.194	-	,		
vii.	Are reactive and ignitable wastes in tanks protected or rendered non-reactive or nonignitable? Indicate if waste is ignitable or reactive. (If waste is rendered non-reactive or nonignitable, see treatment requirements.) 265.198	Specific Addison		180 Sanskrownski	
viii.	Are incompatible wastes stored in separate tanks? (If not, the provisions of 40 CFR §265.17(b) apply.) 265.199		-		

Yes No NI Remarks

THIS SECTION NOT APPLICABLE

1X.	buffer zone requirements for tanks	the National Fire containing ignitat	Protection Association's ple or reactive wastes?
	Tank capacity:	gallons	
	Tank diameter:	feet	
	Distance of tank from property line	W	feet
	(see tables 2-1 through 2-6 of NFPA Code - 1977" to determine compliance	's "Flammable and e.)	Combustible Liquids
	hazardous waste accumulated in other n tanks or containers?		
d. Per	sonnel training. 262.34 (a) 5	_	•
Do inc	lude occure TEACH EM	S IS FOR INOUSTRIAL, PLOYEES THEY SUPER	ENGINEERS, WHO IN TURN NISE. THERE IS NO RECORD FO US NANDLE THE WASTE.
i.	Job Titles?	<u> </u>	
ii.	Job Descriptions? -	<u> </u>	
iii.	Description of training?	<u> </u>	
iv.	Records of training?		
٧.	Did personnel receive the required training by 5-19-81?	×	
vi.	Do new personnel receive required training within six months?		NO NEW HIRES - QUESTION NOT APPLICABLE
vii.	Do personnel training records indicathat personnel have taken part in a annual review of initial training?		THEREHAS BEEN NO ANNUAL REVIEW; INITIAL TRAINING WAS I
e. Pre	paredness and Prevention 265. Subp	art C	1980,
i.	Maintenance and Operation of Facility:	· · · · · · · · · · · · · · · · · · ·	
e.	Is there any evidence of fire, explorelease of hazardous waste or hazardwaste constituent? 265.31	osion, or dous $\underline{\qquad}$	

ies No

NI.

Remarks

ìi.	If required, does this facility have the following equipment: 265.32	
	Internal communications or alarm systems?	X
	Telephone or 2-way Radios at the scene of operations?	X
	Portable fire extinguishers, fire control, spill control equipment and decontamination equipment?	
	Indicate the volume of water and/or foam	available for fire control:
	100,000 GAL TRAK OF WATER FOR FI	RE CONTROL
iii.	Testing and Maintenance of Emergency Equipm	ent: 265.33
	Has the owner or operator established testing and maintenance procedures for emergency equipment?	<u>×</u>
	Is emergency equipment maintained in operable condition?	<u>× </u>
iv.	Has owner/operator provided immediate access to internal alarms (if needed)?	<u>X</u>
٧.	Is there adequate aisle space for unobstructed movement?	<u>X</u>
vi.	Has the owner or operator attempted to make arrangements with local authorities in case of an emergency at the facility?	<u> </u>
f. Cor	ntingency Plan and Emergency Procedures 265	Subpart D
		NCY PLAN COULD NOT BE POUND, WAS N. EFER INSPECTION.
	i. The actions facility personnel must tak to comply with §265.51 and 265.56 in re to fires, explosions, or any unplanned of hazardous waste? (If the owner has Prevention, Control and Countermeasures Plan, he needs only to amend that plan incorporate hazardous waste management provisions that are sufficient to compl with the requirements of this Part (as applicable.) 265.52	sponse release a Spill (SPCC) to

	SEE PREVIOUS PAGE	res	NO	NI	Remarks
ii.	Arrangements agreed to by local police departments, hospitals, contractors, and State and local emergency response teams to coordinate emergency services, pursuant to §265.37?				
iii.	Names, addresses, and phone numbers (Office and Home) of all persons qualified to act as emergency coordinator.	2		***************************************	
iv.	A list of all emergency equipment at the facility which includes the location and physical description of each item on the list, and a brief outline of its capabilities?				-
٧٠	An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary? (This plan must describe signal(s) to be used to begin evacuation, evacuation routes and alternate evacuation routes?)				
vi.	Are copies of the Contingency Plan availablat site and local emergency organizations?	e		***************************************	-
/ii.	Is the facility emergency coordinator identified?				2013-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
iii.	Is coordinator familiar with all aspects of site operation and emergency procedures?	-	-	- Orni Discol	
ix.	Does the Emergency Coordinator have the authority to carry out the Contingency Plan?		***************************************		
х.	If an emergency situation has occured at this facility, has the emergency coordinator followed the emergency procedures listed in 265.56?	•			

11.005358965

Secti	on D:	: <u>R</u>	ECORDKEEPING AND REPORTING (Part 262, Su	bpart	D) .		
				Yes	No	NI	Remarks
(1)	haza	ardo	test results and analyses needed for us waste determinations retained for three years? 262.40	<u>X</u>	***************************************		
Secti	on E:		NTERNATIONAL SHIPMENTS (Part 262 Subpart 52.50	E)			
(1)		the ardo	installation imported or exported us waste? If "no", skip a and b.		<u>×</u> _		
< .	a.		orting Hazardous Waste, has a generator: Notified the Administrator in writing?		A	OT APP	² LICABLE
	i	ii.	Obtained the signature of the foreign consignee confirming delivery of the waste(s) in the foreign country?	CALVERNA		Modification of the second	
	ţi	ii.	Met the Manifest requirements?	- Rivering	 .	*	
	b.	Impo geno	orting Hazardous Waste, has the erator met the manifest requirements?	One Administration		NOT APP	CLICABLE